

HISTORIC AMERICAN BUILDINGS SURVEY

Index to Photographs

HABS  
MASS  
9-MED,  
7-

Addendum to  
George Blanchard House  
18 Bradbury Avenue  
Medford  
Middlesex County  
Massachusetts

HABS No. MA-2-5

Photographs MA-2-5-1 through MA-2-5-5 previously submitted to Library of Congress.

MA-2-5-6 through MA-2-5-23 by Orville Carroll, photographer, July 1968

MA-2-5-6	WEST PARLOR, FIRST FLOOR, NORTH WALL WITH LEAN-TO BEYOND
MA-2-5-7	WEST PARLOR, FIRST FLOOR, EAST WALL
MA-2-5-8	WEST PARLOR, FIRST FLOOR, SOUTH WALL
MA-2-5-9	WEST PARLOR, FIRST FLOOR, WEST WALL
MA-2-5-10	EAST PARLOR, NORTH WALL WITH VIEW OF KITCHEN BEYOND
MA-2-5-11	EAST PARLOR, EAST WALL
MA-2-5-12	EAST PARLOR, SOUTH WALL
MA-2-5-13	EAST PARLOR, WEST WALL
MA-2-5-14	KITCHEN, LOOKING WEST
MA-2-5-15	REAR NORTH ROOM, STEPS TO LOWER ROOM LEVEL AND CELLAR BEYOND
MA-2-5-16	REAR WEST ROOM, WEST EXTERIOR WALL SHOWING OLD DOORWAY, CLOSED OFF
MA-2-5-17	WEST CHAMBER, EAST WALL
MA-2-5-18	WEST CHAMBER, SOUTH WALL
MA-2-5-19	EAST CHAMBER, VIEW LOOKING NORTHEAST
MA-2-5-20	EAST CHAMBER, SECOND FLOOR, SOUTH END OF THE EAST WALL
MA-2-5-21	EAST CHAMBER, SOUTH WALL
MA-2-5-22	EAST ATTIC ROOM, SOUTH SIDE OF SLOPING CEILING SHOWING EARLY SPLIT LATH AND PLASTER FINISH AGAINST ROOF SHEATHING
MA-2-5-23	WEST ATTIC ROOM WITH ROOF STRUCTURE EXPOSED

MA-2-5-24 through MA-2-5-31 by George M. Cushing, photographer, July 1968

MA-2-5-24	EAST PARLOR, DETAIL OF WEST WALL, SHOWING LOCATION OF FORMER CELLAR DOOR
MA-2-5-25	KITCHEN FIREPLACE, PARTIALLY DEMOLISHED, SHOWING MILL STONE
MA-2-5-26	FRAMING DETAIL, FIRST FLOOR LEAN-TO
MA-2-5-27	WEST CHAMBER, DETAIL OF SOUTHWEST CORNER POST
MA-2-5-28	EAST CHAMBER, NORTHEAST CORNER
MA-2-5-29	SCARF JOINT, REAR PLATE, EAST CHAMBER
MA-2-5-30	LEAN-TO, SECOND FLOOR, EARLY WINDOW OPENINGS
MA-2-5-31	ROOF STRUCTURE, WEST ATTIC ROOM, DETAIL